

Worksite: 15-309 general repairs

Date: 04-07-18

JBT06 opened lid @ 915 EDT

V.S DEPTH @ 924 EDT 6 4/16"

FLOW @ 930 EDT 2.66, 2.75, 2.56, 2.71, 2.66

DEPTH: 3 14/16"

AVERAGE?

V.S DEPTH @ 932 EDT 6 7/16"

CLOSED LID @ 936 EDT

JBT18 black solar cable unplugged
from solar controller. Re-saved @ ~900 EDT

RETURNED

JBT14 REPLACED ISCD @ JBT14 @ ~1030 EDT

DUE TO FLOWMETER CEASING TO FUNCTION

AFTER REMOVAL, HAD INITIALLY REMOVED TO
REPAIR

15.5575
15.875

15.5575
15.7165

Scale: 1 square =

Rite in the Rain